

## LAB ANALYSIS REPORT

<b>Company:</b> RVI 304 Industrial Drive Redwood Falls, MN 56283	<b>Date:</b> April 20, 2010
<b>Submitted by:</b> Doug Houle <b>Ph.</b> 507-644-3227	<b>Report No.:</b> 10-0238
	<b>P. O. No.:</b> 012622-001
	<b>Page 1 of 5</b>

### IDENTIFICATION

Vendor:  
Part Number:  
Description:  
Quantity Received: 2  
Request No.: N/A

### BACKGROUND INFORMATION

Received two (Q7, Q21/TO-247AD package) for analysis.

Package markings: 20N60CFD GHD840

### SUMMARY OF ANALYSIS PROCESS (Numbered in Order Completed)

<u>    </u> Electrical Test	<u>  3  </u> Detailed Internal/External Analysis
<u>  1  </u> Curve Tracer	<u>  5  </u> Scanning Electron Microscope (SEM)
<u>    </u> Bake and Retest 2 Hours at 180°C	<u>    </u> Energy Dispersive X-Ray (EDX) Analysis
<u>    </u> X-Ray	<u>    </u> Cross-Section
<u>  2  </u> Decapsulate <u>    </u> Mechanical <u>  X  </u> Chemical	<u>  4  </u> Delayer Die Surface for SEM Analysis

**PREPARED BY:**



**REVIEWED BY:**



THIS TEST REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, WITHOUT WRITTEN APPROVAL FROM THE SPECIALTY LAB, INC  
The tests indicated in the applicable plan and purchase order were performed using standard laboratory techniques, due care in performance and reasonable technical judgment. However, The Specialty Lab, Inc. assumes no responsibility or liability for any use made of this data by the purchaser.

## **ANALYSIS**

Both MOSFETS were verified as having a gate, source, drain short.

Decap revealed severe EOS/localized heat damage beneath the source wire bond on the die surface.

The MOSFETS were delayered on the die surface for SEM analysis.


## **CONCLUSION/COMMENTS**

Both MOSFETS were shorted due to EOS/localized heat damage on the die surface, originating beneath the source wire bond.

Three possible causes are: 1) excessive current flow, 2) partially turned on gate and/or 3) inadequate cooling/heatsinking of the MOSFETS.


**Figure 1.**

**Overall view of the MOSFET package.**




**Figure 2.**

**View of the package markings including the vendor logo. Same on both MOSFETS.**




**Figure 3.**

**Optical view of the dip surface of Q7, illustrating the EOS/localized heat damage at the source wirebond area (arrow).**



**Figure 4.**


**View of the die surface of Q21, illustrating the EOS/localized heat damage (arrow).**





**Figure 5.**  
16X

**SEM view of the delayered die surface of Q7, illustrating the localized heat damaged area (arrow).**



**Figure 6.**  
60X

**Closer SEM view of the localized heat damaged area of Q7. Intense heating caused melting of the silicon bulk.**



**Figure 7.**  
17X

**SEM view of Q21, illustrating the hole in the silicon bulk (arrow) due to intense heating.**



**Figure 8.**  
90X

**Closer SEM view of the localized heat damaged area of Q21.**

