

CUSTOMER NAME	:	5)	RMA#	:	
CUSTOMER P/N	:		RMATS#	:	
MANUFACTURE NAME	:	Artesyn Technologies	CUST. REF#	:	LSU0020877
MANUFACTURE P/N	:	7000977-Y000	RVI WORK ORDER #	:	378411
FAILURE LOCATION	:		DATE RECEIVED	:	08-27-07

		UNIT INFO	ORMATION	
SERIAL NO.	DATE CODE	REVISION	QTY	REASON FOR RETURN
0025838-0709108305	0709	F	1	Functional Failure

CUSTOMER'S FAILURE DESCRIPTION Breaker AC1 Tripped


RVI VERIFICATION		March State of the Party of the State of the	
	Failure symptom	Vis	ual Inspection
	AC1 Breaker Tripped	Solder spla	ash across legs of Q12
FAILURE ANALYSIS		Note that the second second	
Investigation & Analysis			
splash provided "48VIN trip when the "Fused 48 Component : Solde	n Q12. The solder splash was acro " or return potential to be applied V" was present. er splash on Q12 causing it to trigge	to the trip coil connection, caus	sing the breaker to
Measurement Component :			
PROBABLE CAUSE	A STATE OF THE PARTY OF THE PAR		
Workmanship issue from	n the factory.		
Classification of Failure :	Design Problem :	Workmanship	: X
	Component Problem :	Handling Problem	;
	Process Problem :	Others	:

ATTACHMENT	
4 Photos	

Product: Failure Analysis Report Form


Revision: C






Product: Failure Analysis Report Form Revision: C






Product: Failure Analysis Report Form Revision: C





Product: Failure Analysis Report Form Revision: C





PREPARED BY:	REVIEWED BY:	APPROVED BY : Dan Schmid	
Chad Rosenberg	Doug Houle		
Repair Technician	Engineer	Operations Manager	

Product: Failure Analysis Report Form

Revision: C